

SANBAG

San Bernardino Associated Governments Monthly Construction Report State Route 30/210

Construction through November 2001



Segment 1: View looking east at the embankment fill between the LA/SB County Line and Benson Avenue.



Segment 1: View looking east at the construction of Drainage System No. 4 pipe and drainage structures.



Segment 2: Photo of Retaining Wall No. 126. San Antonio Avenue Overcrossing shown in the photo.



Segment 2: Pipe delivered to site for Drainage System No. 1 outfall. Euclid Avenue Overcrossing shown in background.



Segment 3: Distant photo of the length of Soil Nail Wall No. 167.



Segment 4: Construction of retaining wall forms with architectural treatment on Retaining Wall No. 205.

SANBAG

San Bernardino Associated Governments Monthly Construction Report State Route 30/210

Construction through November 2001



Segment 4: Construction of the access at Deer Creek Channel.